Sanitized Copy Approved for Rel	ease 2011/03/02 : CIA-RDP82-00)457R006200370001-6	50X1-HUM
LEGFAX 11		•	
	a/Johradl/US of Islab o.	ПХ	
COUNTRY Soviet Some of Germany	REPORT	-	
TURES Alt Loennewitz Airfield	CONFIDENTIAL		
	in annimik mada dar salah kanan anni salah kakan annimik makan kanan kanan ing mengan kanan kanan kanan kanan	XX-4 Machinelle Long Street of the College Col	
EVALUATION			50X1-HUM
DATE OF CONT	and managed with the second	1478 N FRANCIS AND	
DATE OBTAINE	DATE PREPARED 13 Oct	ober 1950	
REFERENCES_	and demonstrate property follows and property and the control of t	and a second	
PAGES 2 ENCLOSURES (NO. & T	/PE)		
REMARKS	·*		
		5	50X1-HUM
	TO A	Maria Manga	Popul (a the Martin man or capital, and a six to account in the party
	An TOTAL OF MEMORIPHY ALL IS MAY VARIE AND AND WASHINGTON AND THE AND AN AND AN AND AND AND AND AND AND A	- COMMINISTRAÇÃO (PARTE) E E PROTECTO A COMPANION A COMPANION A COMPANION DE ACOMPANION A COMPANION A	NAME OF STREET OF STREET STREET, STREE
A A LICENSE MAN MAN CONTINUE STATE AND ADMINISTRATION OF THE PROPERTY OF THE P	dende man, med des blackes as lares d'anno se motors hait in a descrió, sebre i delle veta le motoridate d'anticiones audis anno	50X1-HUM	to PARTIE VOICE CONTROL CONTROL VALUE OF

 There was no flying at the Alt Loennewitz (U 52/E 8h) airfield between 7 and 9 p.m. on 15 deptember 1050. The obstacle lights but not the runway lights were switched on. From six to eight planes were purked in a hangar which was open and lighted.


2. The field was observed between 3:30 and 9 p.m. on 19 September 1950. Hine jet planes with high rudder assembly sloping to the rear were parked in a row on the landing field, four planes of the same type were on the eastern end of the runway and six to eight planes in front of the hangars. (1) All aircraft had their air intake apertures covered with red sheet metal. (2) The hangars were closed. Two single-engine low-wing monoplanes made flights lasting about 30 minutes in occasional rain with a cloudy sky. Description of single-engine, low-wing monoplane : two-seater cockpit, antenna rod forward of cabin, Pitot tube in left wing, radial engine with red propeller hub, tail wheel not retractable, intake tube or oil cooler under engine on left side, trim tab on left alleron, white squares on underside of left wing; guas or machine guns which could not definitely be seen were in the wings close to the fuselage. (3)

- 3. Flying was practiced at an altitude of about 2,000 meters. The planes repeatedly vanished behind thick clouds. During the flying a truck with a radio mast about 5 meters high, and about 30 men, possibly student pilots, were north of the eastern end of the runway. Three of four trucks and from 10 to 12 passenger cars were nearby. A blue, biaxial trailer without windows was in front of the flight control station. A plane landed at 5:55 p.m. and the obstacle light was wwitched on for about 3 minutes as it was raining and visibility was limited.
- 4. One single-engine, low-wing monoplane and 23 jet fighters with swept-back wings were counted at the field on 20 September 1950. (1) The hangars were closed. Four jet fighters and the single-engine, low-wing nonoplane practiced flying between 2:30 and 4 p.m. There were only small cloud gaps and it occasionally rained. The jet fighters took off at intervals of about 30 seconds, lifted off the



50X1-HUM

50X1-HUM



ground at a speed of about 250 km/h, climbed to an altitude of about 1,000 meters in about 2 minutes, and flew over the field above the cloud base. The planes landed at 3 p.m. and took off again at 3:30 p.m. The single-engine, low-wing monoplane made the same flights as on the day before. Two radio trucks were at the eastern end of the runway. One truck had an antenna about 6 meters high, the other had two antennas at the rear wall which pointed upward to the rear and one antenna forward on the roof. About 150 men were standing on the landing field in serveral groups. A device with a shield but without a barrel was in the southeastern section of the landing field. It resembled a gum. (4)


- 5. On 20 September 1950 there was no flying at the field after dusk although the weather was good. The lights were not switched on and the aircraft remained on the landing field.
- 6. The runway lights, searchlights on poles about 30 cm high, were still there. A small wooden hut with a radio tower about 10 meters high, was in the extension of the runway to the east. The field was strictly guarded. The view was limited on the southern edge by a board fence which was a out 2.2 meters high. A Soviet guard detail of four to six man was stationed in Alt Loennewitz.

cannot be determined.

50X1-HUM

	Corments.		
1)			
2)	The lid on the air intake aperture was apparently a protection against dust.		
4	va cur v o		
3)	From the description the planes are Yak-11 trainers. The type or use of the device in the southeastern section of the field		

50X1-HUM



CONFIDENTIAL